

08-Auto HVAC -- Status: Malfunction 0010  
15-Airbags -- Status: Malfunction 0010  
16-Steering wheel -- Status: Malfunction 0010  
17-Instruments -- Status: Malfunction 0010  
44-Steering Assist -- Status: Malfunction 0010  
46-Central Conv. -- Status: Malfunction 0010

---

Address 08: Auto HVAC    Labels: 8P0-820-043.LBL  
Part No SW: 8P0 820 043 AH    HW: 8P0 820 043 AH  
Component: KlimavollautomatH19 0430

1 Fault Found:

00796 - Fan for Interior Temp Sensor (V42)

011 - Open Circuit - Intermittent

Freeze Frame:

Fault Status: 00101011

Fault Priority: 3

Fault Frequency: 30

Reset counter: 77

Mileage: 106316 km

Time Indication: 0

Date: 2016.03.30

Time: 05:32:18

Freeze Frame:

Voltage: 10.80 V

Temperature: 5.5°C

---

Address 15: Airbags    Labels: None  
Part No SW: 8P0 959 655 N    HW: 8P0 959 655 N  
Component: Airbag 9.41 H01 4230  
Coding: 0070612  
Shop #: WSC 06314

1 Fault Found:

01587 - Igniter 2 for Airbag; Drivers Side (N250)

001 - Upper Limit Exceeded - MIL ON

Freeze Frame:

Fault Status: 11100001

Fault Priority: 1

Fault Frequency: 1

Mileage: 110850 km

Time Indication: 0

Date: 2016.09.09

Time: 00:05:48

---

Address 16: Steering wheel    Labels: 8P0-953-549.LBL  
Part No SW: 8P0 953 549 F    HW: 8P0 953 549 F  
Component: J0527    H36 0070  
Coding: 0002042

Shop #: WSC 06314

Part No: XXXXXXXXXXXXX

Component: E0221 H02 0030

2 Faults Found:

00883 - Ignition Switch (D) Terminal S

012 - Electrical Fault in Circuit - Intermittent

01426 - Controls in Steering Wheel (E221)

004 - No Signal/Communication - Intermittent

---

Address 17: Instruments Labels: 8P0-920-xxx-17.LBL

Part No SW: 8P0 920 931 E HW: 8P0 920 931 E

Component: KOMBIINSTR. VDO H22 0660

Coding: 0004128

Shop #: WSC 05430

1 Fault Found:

00003 - Control Module

005 - No or Incorrect Basic Setting / Adaptation

Freeze Frame:

Fault Status: 01100101

Fault Priority: 6

Fault Frequency: 1

Mileage: 49104 km

Time Indication: 0

Date: 2012.01.20

Time: 16:35:44

---

Address 44: Steering Assist Labels: 1Kx-909-14x.LBL

Part No: 1K1 909 144 M

Component: EPS\_ZFLS K1.079 H08 1901

1 Fault Found:

00778 - Steering Angle Sensor (G85)

000 - -

---

Address 46: Central Conv. Labels: 8P0-959-433.LBL

Part No: 8P0 959 433 L

Component: KSG H11 0080

Coding: 1880202002186D298505488A0167

Shop #: WSC 06314

Component: Sounder n.mounted

Component: NGS n.mounted

Component: IRUE n.mounted

1 Fault Found:

00849 - S-contact at Ignition/Starter Switch (D)  
008 - Implausible Signal - Intermittent